



# MACHINING OPERATIONS AND MACHINE TOOLS

---

1. Turning and Related Operations
2. Drilling and Related Operations
3. Milling
4. Machining Centers and Turning Centers
5. Other Machining Operations
6. High Speed Machining



# Machining

---

A material removal process in which a sharp cutting tool is used to mechanically cut away material so that the desired part geometry remains

- Most common application: to shape metal parts
- Most versatile of all manufacturing processes in its capability to produce a diversity of part geometries and geometric features with high precision and accuracy
  - Casting can also produce a variety of shapes, but it lacks the precision and accuracy of machining

# Classification of Machined Parts

- Rotational - cylindrical or disk-like shape
- Nonrotational (also called prismatic) - block-like or plate-like






Figure 22.1 Machined parts are classified as: (a) rotational, or (b) nonrotational, shown here by block and flat parts.



# Machining Operations and Part Geometry

---

Each machining operation produces a characteristic part geometry due to two factors:

1. Relative motions between tool and workpart
  - *Generating* – part geometry determined by feed trajectory of cutting tool
2. Shape of the cutting tool
  - *Forming* – part geometry is created by the shape of the cutting tool

# Generating Shape




Figure 22.2 Generating shape: (a) straight turning, (b) taper turning, (c) contour turning, (d) plain milling, (e) profile milling.

# Forming to Create Shape




Figure 22.3 Forming to create shape: (a) form turning, (b) drilling, and (c) broaching.

# Forming and Generating




Figure 22.4 Combination of forming and generating to create shape:  
(a) thread cutting on a lathe, and (b) slot milling.



# Turning

---

Single point cutting tool removes material from a rotating workpiece to generate a cylinder

- Performed on a machine tool called a *lathe*
- Variations of turning performed on a lathe:
  - Facing
  - Contour turning
  - Chamfering
  - Cutoff
  - Threading



# Turning





Figure 22.5 Turning operation.

# Turning Operation

Close-up view of a turning operation on steel using a titanium nitride coated carbide cutting insert (photo courtesy of Kennametal Inc.)



# Facing

Tool is fed  
radially inward




Figure 22.6 (a) facing

(a)

# Contour Turning

- Instead of feeding tool parallel to axis of rotation, tool follows a contour that is other than straight, thus creating a contoured shape




Figure 22.6 (c) contour turning

# Chamfering

- Cutting edge cuts an angle on the corner of the cylinder, forming a "chamfer"




Figure 22.6  
(e) chamfering

(e)



# Cutoff

- Tool is fed radially into rotating work at some location to cut off end of part




Figure 22.6 (f) cutoff

# Threading

- Pointed form tool is fed linearly across surface of rotating workpart parallel to axis of rotation at a large feed rate, thus creating threads




Figure 22.6 (g) threading

(g)

# Engine Lathe




Figure 22.7  
Diagram of an  
engine lathe,  
showing its  
principal  
components





# Methods of Holding the Work in a Lathe

---

- Holding the work between centers
- Chuck
- Collet
- Face plate

# Holding the Work Between Centers




Figure 22.8 (a) mounting the work between centers using a "dog"

# Chuck




Figure 22.8 (b) three-jaw chuck

# Collet




Figure 22.8 (c) collet

# Face Plate




Figure 22.8 (d) face plate for non-cylindrical workparts



# Turret Lathe

---

Tailstock replaced by “turret” that holds up to six tools

- Tools rapidly brought into action by indexing the turret
- Tool post replaced by four-sided turret to index four tools
- Applications: high production work that requires a sequence of cuts on the part



# Chucking Machine

---

- Uses chuck in its spindle to hold workpart
- No tailstock, so parts cannot be mounted between centers
- Cutting tool actions controlled automatically
- Operator's job: to load and unload parts
- Applications: short, light-weight parts



# Bar Machine

---

- Similar to chucking machine except collet replaces chuck, permitting long bar stock to be fed through headstock
- At the end of the machining cycle, a cutoff operation separates the new part
- Highly automated (a.k.a. *automatic bar machine*)
- Applications: high production of rotational parts





# Automatic Screw Machine

---

- Same as automatic bar machine but smaller
- Applications: high production of screws and similar small hardware items



# Multiple Spindle Bar Machines

---

- More than one spindle, so multiple parts machined simultaneously by multiple tools
  - Example: six spindle automatic bar machine works on six parts at a time
- After each machining cycle, spindles (including collets and workbars) are indexed (rotated) to next position

# Multiple Spindle Bar Machine




Figure 22.9 (a) Part produced on a six-spindle automatic bar machine; and (b) sequence of operations to produce the part: (1) feed stock to stop, (2) turn main diameter, (3) form second diameter and spotface, (4) drill, (5) chamfer, and (6) cutoff.



# Boring

---

- Difference between boring and turning:
  - Boring is performed on the inside diameter of an existing hole
  - Turning is performed on the outside diameter of an existing cylinder
- In effect, boring is internal turning operation
- Boring machines
  - Horizontal or vertical - refers to the orientation of the axis of rotation of machine spindle

# Vertical Boring Mill




Figure 22.12 A vertical boring mill – for large, heavy workparts.

# Drilling

- Creates a round hole in a workpart
- Compare to boring which can only enlarge an existing hole
- Cutting tool called a *drill* or *drill bit*
- Machine tool: *drill press*




Figure 21.3 (b) drilling

# Through Holes vs. Blind Holes

Through-holes - drill exits opposite side of work

Blind-holes – does not exit work opposite side




Figure 22.13 Two hole types: (a) through-hole, and (b) blind hole.

# Reaming

- Used to slightly enlarge a hole, provide better tolerance on diameter, and improve surface finish




Figure 22.14 Machining operations related to drilling: (a) reaming



# Tapping

- Used to provide internal screw threads on an existing hole
- Tool called a *tap*




Figure 22.14 (b) tapping

# Counterboring

- Provides a stepped hole, in which a larger diameter follows smaller diameter partially into the hole




Figure 22.14 (c) counterboring

# Drill Press

- Upright drill press stands on the floor
- Bench drill similar but smaller and mounted on a table or bench





Figure 22.15 Upright drill press

# Radial Drill

Large drill press  
designed for  
large parts

Figure 22.16 Radial drill press  
(photo courtesy of Willis  
Machinery and Tools).





# Work Holding for Drill Presses

---

- Workpart in drilling can be clamped in any of the following:
  - *Vise* - general purpose workholder with two jaws
  - *Fixture* - workholding device that is usually custom-designed for the particular workpart
  - *Drill jig* – similar to fixture but also provides a means of guiding the tool during drilling



# Milling

---

Machining operation in which work is fed past a rotating tool with multiple cutting edges

- Axis of tool rotation is perpendicular to feed
- Creates a planar surface
  - Other geometries possible either by cutter path or shape
- Other factors and terms:
  - Interrupted cutting operation
  - Cutting tool called a milling cutter, cutting edges called "teeth"
  - Machine tool called a milling machine

# Two Forms of Milling




Figure 21.3 Two forms of milling: (a) peripheral milling, and (b) face milling.



# Peripheral Milling vs. Face Milling


---

- Peripheral milling
  - Cutter axis parallel to surface being machined
  - Cutting edges on outside periphery of cutter
- Face milling
  - Cutter axis perpendicular to surface being milled
  - Cutting edges on both the end and outside periphery of the cutter



# Slab Milling

- Basic form of peripheral milling in which the cutter width extends beyond the workpiece on both sides




(a)

Figure 22.18 (a) slab milling

# Slotting

- Width of cutter is less than workpiece width, creating a slot in the work




(b)

Figure 22.18 (b) slotting

# Conventional Face Milling

Cutter overhangs work  
on both sides




(a)

Figure 22.20 (a) conventional face milling




High speed face  
milling using  
indexable inserts  
(photo courtesy  
of Kennametal  
Inc.).



# End Milling

- Cutter diameter is less than work width, so a slot is cut into part



(c)

Figure 22.20 (c) end milling



# Profile Milling

Form of end milling  
in which the  
outside periphery  
of a flat part is cut




Figure 22.20 (d) profile milling

# Pocket Milling

- Another form of end milling used to mill shallow pockets into flat parts





Figure 22.20 (e) pocket milling

# Surface Contouring

- Ball-nose cutter fed back and forth across work along a curvilinear path at close intervals to create a three dimensional surface form



(f)

Figure 22.20 (f) surface contouring



# Horizontal Milling Machine




Figure 22.23 (a) horizontal knee-and-column milling machine.

# Vertical Milling Machine




Figure 22.23 (b) vertical knee-and-column milling machine



# Machining Centers

---

Highly automated machine tool can perform multiple machining operations under CNC control in one setup with minimal human attention

- Typical operations are milling and drilling
- Three, four, or five axes
- Other features:
  - Automatic tool-changing
  - Pallet shuttles
  - Automatic workpart positioning




Figure 22.26 Universal machining center; highly automated, capable of multiple machining operations under computer control in one setup with minimal human attention (photo courtesy of Cincinnati Milacron).




Figure 22.27 CNC 4-axis turning center (photo courtesy of Cincinnati Milacron); capable of turning and related operations, contour turning, and automatic tool indexing, all under computer control.



# Mill-Turn Centers

---

Highly automated machine tool that can perform turning, milling, and drilling operations

- General configuration of a turning center
- Can position a cylindrical workpart at a specified angle so a rotating cutting tool (e.g., milling cutter) can machine features into outside surface of part
  - Conventional turning center cannot stop workpart at a defined angular position and does not include rotating tool spindles



# Operation of Mill-Turn Center




Figure 22.28 Operation of a mill-turn center: (a) example part with turned, milled, and drilled surfaces; and (b) sequence of operations on a mill-turn center: (1) turn second diameter, (2) mill flat with part in programmed angular position, (3) drill hole with part in same programmed position, and (4) cutoff.

# Shaping and Planing

- Similar operations
- Both use a single point cutting tool moved linearly relative to the workpart




Figure 22.29 (a) Shaping, and (b) planing.





# Shaping and Planing

---

- A straight, flat surface is created in both operations
- Interrupted cutting
  - Subjects tool to impact loading when entering work
- Low cutting speeds due to start-and-stop motion
- Typical tooling: single point high speed steel tools

# Shaper




Figure 22.30 Components of a shaper.

# Planer




Figure 22.31 Open side planer.

# Broaching

- Moves a multiple tooth cutting tool linearly relative to work in direction of tool axis




Figure 22.33 Broaching operation.



# Broaching

---

## Advantages:


- Good surface finish
- Close tolerances
- Variety of work shapes possible

Cutting tool called a *broach*

- Owing to complicated and often custom-shaped geometry, tooling is expensive

# Internal Broaching

- Performed on internal surface of a hole
- A starting hole must be present in the part to insert broach at beginning of stroke



(b)

Figure 22.34 Work shapes that can be cut by internal broaching; cross-hatching indicates the surfaces broached.




# Sawing

---

- Cuts narrow slit in work by a tool consisting of a series of narrowly spaced teeth
- Tool called a *saw blade*
- Typical functions:
  - Separate a workpart into two pieces
  - Cut off unwanted portions of part

# Power Hacksaw




(a)

Figure 22.35 (a) power hacksaw –linear reciprocating motion of hacksaw blade against work.



# Band Saw

Figure 22.35 (b) bandsaw (vertical) – linear continuous motion of bandsaw blade, which is in the form of an endless flexible loop with teeth on one edge.



# Circular Saw




Figure 22.35 (c) circular saw – rotating saw blade provides continuous motion of tool past workpart.



# High Speed Machining (HSM)

---

Cutting at speeds significantly higher than those used in conventional machining operations

- Persistent trend throughout history of machining is higher and higher cutting speeds
- At present there is a renewed interest in HSM due to potential for faster production rates, shorter lead times, and reduced costs



# High Speed Machining

---

## Conventional vs. high speed machining

Indexable tools (face mills)

Work material	Conventional speed		High speed	
	<u>m/min</u>	<u>ft/min</u>	<u>m/min</u>	<u>ft/min</u>
Aluminum	600+	2000+	3600+	12,000 +
Cast iron, soft	360	1200	1200	4000
Cast iron, ductile	250	800	900	3000
Steel, alloy	210	700	360	1200

Source: Kennametal Inc.



## Other HSM Definitions – DN Ratio

---

*DN ratio* = bearing bore diameter (mm) multiplied by maximum spindle speed (rev/min)

- For high speed machining, typical DN ratio is between 500,000 and 1,000,000
- Allows larger diameter bearings to fall within HSM range, even though they operate at lower rotational speeds than smaller bearings



## Other HSM Definitions – HP/RPM Ratio

---

*hp/rpm ratio* = ratio of horsepower to maximum spindle speed

- Conventional machine tools usually have a higher hp/rpm ratio than those equipped for HSM
- Dividing line between conventional machining and HSM is around 0.005 hp/rpm
- Thus, HSM includes 15 hp spindles that can rotate at 30,000 rpm (0.0005 hp/rpm)



# Other HSM Definitions

---

- Emphasis on:
  - Higher production rates
  - Shorter lead times
  - Rather than functions of spindle speed
- Important non-cutting factors:
  - Rapid traverse speeds
  - Automatic tool changes



# Requirements for High Speed Machining

---

- Special bearings designed for high rpm
- High feed rate capability (e.g., 50 m/min)
- CNC motion controls with “look-ahead” features to avoid “undershooting” or “overshooting” tool path
- Balanced cutting tools, toolholders, and spindles to minimize vibration
- Coolant delivery systems that provide higher pressures than conventional machining
- Chip control and removal systems to cope with much larger metal removal rates





# High Speed Machining Applications

---

- Aircraft industry, machining of large airframe components from large aluminum blocks
  - Much metal removal, mostly by milling
- Multiple machining operations on aluminum to produce automotive, computer, and medical components
  - Quick tool changes and tool path control important
- Die and mold industry
  - Fabricating complex geometries from hard materials