

## SIMBOLOGIA PARA CROQUIS RESPECTIVOS ÀS FIXAÇÕES DE PEÇAS EM MÁQUINAS





Symbol	Signification	DOF cancel
	Flat fixed contact on machined surface	1
removable	Flat removable contact on a machined surface	1
	Serrated jaws with concentric clamping floating used as driver on raw surface	2
	Curved fixed contact used as datum for a raw surface	1
	Fixed free contact for datum on a raw surface	4
VN-	Axial pan used as contact point for remachining a machined surface	2
+>	Axial fixed center used as support on a machined center	3
	Axial fixed pan used as datum on a raw surface	2
	Swing bar with serrated surfaces for positioning on a raw surface	. 1
=	Axial sliding vee used as datum on a machined surface	1
w->	Axial center with spring used as datum on machined center	2
~ D	Axial rotating center of tail stock used as short centering and locking	2
<b>&gt;</b>	Complete fixed center in a machined hole Free fixed center (locating) in a machined hole	2
	Irreversible support element, jack against vibrations	0
4//->	Spacer against vibrations or support for parts with thin walls	0.