

FIGURE 7.102 **Lead Screw Bracket. Draw or sketch necessary views (Layout C–3 or A2–3).***