

Tabela 5				
Pontos	V (V)	FE Usado (V)	I (mA)	FE Usado (mA)
1	-0,0234	400mV	-2,20	40
2	-2,235	4	-21,87	40
3	-1,903	4	-18,67	40
4	-2,394	4	-23,45	40
5	-3,175	4	-31,11	40
6	-2,940	4	-28,81	40
7	-2,577	4	-25,24	40
8	-1,970	4	-19,31	40
9	0,934	4	9,18	40
10	1,942	4	19,04	40
11	3,169	4	31,04	40
12	2,558	4	25,07	40
13	2,401	4	23,58	40
14	6,37	40	61,6	200
15	3,273	4	32,09	40
16	17,32	40	167,7	200

Tabela 6				
Pontos	V (V)	FE Usado (V)	I (mA)	FE Usado (mA)
1	-0,525	4	-9,27	40
2	-13,37	40	-62,7	200
3	-9,64	40	-50,5	200
4	-7,85	40	-44,4	200
5	-18,36	40	-75,7	200
6	-1,918	4	-20,50	40
7	-17,55	40	-73,9	200
8	-15,40	40	-68,5	200
9	5,66	40	37,76	40
10	2,488	4	23,22	40
11	1,277	4	15,67	40
12	8,93	40	49,2	200
13	6,58	40	41,0	200
14	4,12	40	31,35	40
15	8,77	40	48,7	200
16	4,76	40	34,17	40