

Tabela 5				
Pontos	V (V)	FE Usado (V)	I (mA)	FE Usado (mA)
1	-1,173	4	-11,65	40
2	2,168	4	21,54	40
3	-2,528	4	-25,10	40
4	3,891	4	38,64	40
5	4,43	40	43,7	200
6	4,93	40	48,7	200
7	-5,65	40	-55,7	200
8	6,11	40	60,3	200
9	-7,08	40	-69,7	200
10	7,82	40	77,0	200
11	-8,18	40	-80,6	200
12	9,15	40	90,1	200
13	-9,75	40	-96,0	200
14	10,45	40	102,8	200
15	11,39	40	112,0	200
16	-13,77	40	-135,2	200

Tabela 6				
Pontos	V (V)	FE Usado (V)	I (mA)	FE Usado (mA)
1	-0,0073	400mV	-0,26	40
2	1,289	4	17,55	40
3	-2,253	4	-22,89	40
4	3,118	4	27,46	40
5	-4,000	4	-31,58	40
6	6,01	40	39,60	40
7	-9,60	40	-52,8	200
8	10,94	40	56,6	200
9	14,18	40	66,3	200
10	-14,65	40	-67,6	200
11	17,82	40	75,8	200
12	19,27	40	79,4	200
13	-20,22	40	-81,7	200
14	-23,25	40	-88,6	200
15	23,84	40	89,8	200
16	-25,91	40	-94,2	200